

The images are taken of a cam from a food processing machine. The customer is one of the biggest food producers in the UK.

The cam has worn significantly and the machine is over 40 years old so parts are no longer available. We have scanned and reverse engineered the part in order for us to machine a replacement parts and bring the machine back into full production.



